UNCLASSIFIED

AD NUMBER

AD801411

CLASSIFICATION CHANGES

TO: unclassified

FROM: confidential

LIMITATION CHANGES

TO:

Approved for public release, distribution unlimited


FROM:

Distribution: DoD only: others to Director, Defense Atomic Support Agency, Washington, D. C. 20301.

AUTHORITY

DSWA ltr., 18 Apr 1997; DSWA ltr., 18 Apr 1997

THIS PAGE IS UNCLASSIFIED



CHO ASSIELLU (14) XRD-139

BUREAU OF SHIPS GROUP
TECHNICAL IN ECTION REPORT.

6 Operation Crossroads. USS 457 220.

(1) 1946) (12) 31P.

Downgraded at 3 fear intervals; Declassified after 12 years

APPROVED:

F.X. Forest, Captain, U.S.N.

USS LST 220

Page 1 of 31 Pages

193 600

on the fit of the state of the

UNCTASSITION OF DATE OF THE PARTY OF THE PAR

e po

X

UNUEASSIFIED




TABLE OF CONTENTS

	PAGE NO.
Ship Characteristics Sheet	3
Midship Section	4
Overall Summary of Damage	5
Hull Technical Inspection Report (Section I)	11
Machinery Technical Inspection Report (Section II) -	16
Electrical Technical Inspection Report (Section III) -	21
Photographic Section (Section IV)	27
Commanding Officers Report (Appendix)	30

SECRET

USS LST 220

Page 2 of 31 Pages

Larsellication	(Garrelle	the Chan	ged to	UNFICENTIAL STATES	
By Harry o	# 10.	CLES OF	Sunt Co	TITY TO DATE OF THE STATE OF TH	i.e.
V					مر بر

UNCLASSIFIED

U.S.S. LST 220

SHIP CHARACTERISTICS

Building Yard: Chicago Bridge and Iron Co., Seneca, Illinois.

Commissioned: 26 August 1943.

HULL

Length Overall: 328 feet 0 inches.

Length on Waterline: 316 feet 0 inches.

Beam (extreme): 50 feet 0 inches.

Drufts at time of test: Fwd. 6 feet 3 inches.

Aft. 12 feet 8 inches.

Limiting displacement: 4,080 tons.

Displacement at time of test: 3,404 tons.

MAIN PROPULSION PLANT

Main Engines: Two General Motors Diesels, type,

12 - 567 A. One per main shaft.

Reduction Gears: Type: "Falk" - Single reduction.

One per engine.

Propellors: Two are installed in ship. Main Shafts: Two are installed in ship.


Ships Service Generators: Three - 100 KW. - 230

volts D.C. units are installed.

SECRET

USS LST 220

Page 3 of 31 Pages



MIDSHIP SECTION.
TEST B

SECRET

PAGE 4 OF 31

LST 220

9085

TECHNICAL INSPECTION REPORT

OVERALL SUMMARY

- I. Target Condition After Test.
 - (a) Drafts after test; list; general areas of flooding, sources.

 There was no flooding, hence no change in drafts or list.
 - (b) Structural damage.

HULL

None.

MACHINERY

No comment.

ELECTRICAL

There was no structural damage in way of electrical equipment.

(c) Other damage.

HULL .

Not observed.


MACHINERY

There is no damage to machinery of this vessel, insofar as can be determined by visual inspection. No machinery on this vessel was operated after Test B.

SECRET

USS LST 220

Page 5 of 31 Pages



MIDSHIP SECTION TEST B

SEGNET

PAGE 4 OF 31

LST 220

9085

TECHNICAL INSPECTION REPORT

OVERALL SUMMARY

- I. Target Condition After Test.
 - (a) Draft after test; list; general areas of flooding, sources.

 There was no flooding, hence no change in drafts or list.
 - (b) Structural damage.

HULL

None.

MACHINERY

No comment.

ELECTRICAL

There was no structural damage in way of electrical equipment.

(c) Other damage.

HULL .

Not observed.

MACHINERY

There is no damage to machinery of this vessel, insofar as can be determined by visual inspection. No machinery on this vessel was operated after Test B.

SECRET

USS LST 220

Page 5 of 31 Pages

ELECTRICAL

No damage occurred to electrical equipment due to Test B.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of heat in way of electrical equipment.

(b) Fires and explosions.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

There were no fires or explosions in way of electrical equipment.

USS LST 220

Page 6 of 31 Pages

(c) Snock.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of shock in way of electrical equipment.

(d) Pressure.

HULL

None.

MACHINERY

No evidence.

ELECTRICAL

There was no evidence of pressure in way of electrical equipment.

(e) Effects peculiar to the atom bomb.

KULL

None.

MACHINERY

Nor .

USS LST 220

Page 7 of 31 Pages

ELECTRICAL

Evidence of radioactivity was the only effect noted which was peculiar to the atom bomb.

- III. Results of Test on Target.
 - (a) Effect on machinery, electrical, and ship control.

HULL

Not observed.

MACHINERY

None.

ELECTRICAL

No damage was apparent to electrical machinery or ship control.

(b) Effect on gumnery and fire control,

HULL

Not observed.

MACHINERY

No comment.

ELECTRICAL

No damage was apparent to gunnery and fire control.

SECRET

USS LS 0 220

Page 8 of 31 Pages

(c) Effect on watertight integrity and stability.
HULL
None.
MACHINERY
No comment.
ELECTRICAL
No electrical damage affected watertight integrity or stability.
(d) Effect on personnel and habitability.
HULL
None.
MACHINERY
None.
ELECTRICAL
No electrical damage affected personnel or habitability.
(e) Effect on fighting efficiency.
HULL
The only effect on the fighting efficiency is that resulting from radiological contamination.
MACHINERY
None.
SECRET USS LST 220
Page 9 of 31 Pages

:

PPPCILITONE

No electrical damage affected the fighting efficiency of the vessel.

IV. Summary of Observers' Impressions and Conclusions.

HULL

None.

MACHINERY

LST 220 was outside the effective range of the explosion during Test B.

ELECTRICAL

No damage was evident on any electrical equipment on this vessel. It appears that present electrical equipment has sufficient shock resistance to withstand the effects of the B Bomb at the distance of this vessel from the center of the blast.

Preliminary Recommendations.

HULL

None.

MACHUNERY

None.

ELECTRICAL

None.

SECRET

USS LST 220

Page 10 of 31 Pages

TECHNICAL INSPECTION REPORT

SECTION I - HULL

GENERAL SUMMARY OF HULL DAMAGE

- I. Target Condition After Test.
 - (a) Drafts after test; list; general areas of flooding, sources.

There was no flooding, hence no change in drafts or

list.

(b) Structural damage.

None.

(c) Other damage.

Not observed.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

None.

(b) Fires and Explosions.

None.

(c) Shock.

None.

(d) Pressure.

None.

(e) Effects peculiar to the Atomic Bomb.

None.

SECRET

USS LST220

Page 11 of 31 Pages

Effects of Damage. (a) Effect on machinery, electrical, and ship control. Not observed. (b) Effect on gunnery and fire control. Not observed. (c) Effect on watertight integrity and stability. None. (d) Effect on pursonnel and habitability. None. (e) Effect on fighting efficiency. The only effect on the fighting efficiency is that resulting from radiological contamination. Summary of Observers' Impressions and Conclusions. None. Preliminary General or Specific Recommendations of Inspection Group. None.

III.

v.

THENK

Instructions for loading the vessel specified the following: VI.

II E M	LOADING
Fuel oil	Minimum
Diesel oil	Minimum
Ammunition	10%
Potable and reserve feed water	95%
Salt water ballast	No restriction
SECRET	USS LST220

LOADING

Page 12 of 31 Pages

Details of the actual quantities of the various items aboard are included in Report 7, Stability Inspection Report, submitted by the ship's force in accordance with "Instructions to Target Vessels for Tests and Observations by Ship's Force" issued by the Director of Ships Material. This report is available for inspection in the Bureau of Ships Crossroads Files.

SECRET

>.

USS LST220

Page 13 of 31 Pages

DETAILED DESCRIPTION OF HULL DAMAGE

A. General Description of Hull Damage.

No da ge. General views of the ship after Test B are on pages 2δ and ω .

B. Superstructure.

No damage.

C. Turrets, Guns, and Directors.

No damage.

D. Torpedo Mounts, Depth Charge Gear.

Not applicable.

E. Weather Deck.

No damage.

F. Exterior Hull.

No damage.

G. Interior Compartments (above w.l.).

No damage.

H. Armor Decks and Miscellaneous Armor.

Not applicable.

I. Interior Compartments (below w.l.).

No damage.

SECRET

USS LST 220

Page 14 of 31 Pages

Underwater Hull. Ţ. No damage. Tanks. K. No damage. Flooding. L. None. Ventilation. M. No damage. Ship Control. N. No damage. Fire Control. 0.

No damage.

P. Ammunition Behavior.

No damage.

Q. Ammunition Handling.

No damage.

R. Strength.

No damage.

S. Miscellaneous.

No comment.

SECRET USS IST 220

TECHNICAL INSPECTION REPORT

SECTION II - MACHINERY

GENERAL SUMMARY OF MACHINERY DAMAGE

- I. Target Condition After Test.
 - (a) Drafts after test; list; general areas of flooding, sources.

 No data taken by machinery group.
 - (b) Structural damage.

No comment.

(c) Other damage.

There is no damage to machinery of this vessel, insofar as can be determined by visual inspection. No machinery on this vessel was operated after Test B.

- II. Forces Evidenced and Effects Noted.
 - (a) Heat.

No evidence.

(b) Fires and explosions.

No evidence,

(c) Shock.

No evidence.

(d) Pressure.

No evidence.

SECRET

USS LST 220

(e) Effects apparently peculiar to the atom bomb.

None.

III. Effects of Damage.

- (a) Effect on machinery and ship control.

 None.
- (b) Effect on gumery and fire control.

No comment.

- (c) Effect on water-tight integrity and stability.

 No comment.
- (d) Effect on personnel and habitability.

 None.
- (e) Total effect on fighting efficiency.

None.

IV. General Summary.

LST 220 was outside the effective range of the explosion during Test B.

V. Preliminary Recommendation.

None.

SECRET

USS LST 220

DETAILED DESCRIPTION OF MACHINERY DAMAGE

- A. General Description of Machinery Damage.
 - (a) Overall condition.

The overall condition of the machinery was not changed by Test B.

(b) Areas of major damage.

There are no areas of damage.

- (c) Primary cause of damage in each area of major damage.

 Not applicable.
- (d) Effect of target test on overall operation of machinery plant.

The test had no effect on the operation of the machinery plant.

B. Boilers.

The heating boiler and its accessories were not damaged by Test B.

C. Blowers.

Apparently undamaged.

D. Fuel Oil Equipment.

Apparently undamaged.

E. Boiler Feedwater Equipment.

Apparently undamaged.

SECRET USS LST 220

Page 18 of 31 Pages

F. Main Propulsion Machinery.

No apparent damage.

G. Reduction Gears.

No apparent damage.

H. Shafting and Bearings.

No apparent damage.

I. Lubrication System.

No apparent damage.

J. Condensers and Air Ejectors.

Not applicable.

K. Pumps.

No apparent damage.

L. Auxiliary Generators (Turbines and Gears).

Not applicable.

M. Propellers.

Propellers were inspected from the surface of the water. They are apparently undamaged.

N. Distilling Plant.

No apparent damage.

O. Refrigeration Plant.

No apparent damage.

SECRET USS LST 220

- P. Winches, Windlasses, and Capstans.

 No apparent damage.
- Q. Steering Engine.

No apparent damage.

R. Flevators, Ammunition Hoists, etc.

No apparent damage.

S. Ventilation (Machinery).

No apparent damage.

T. Compressed Air Plant.

No apparent damage.

U. Diesels (Generators and Boats).

No apparent damage.

V. Piping Systems.

No apparent damage.

W. Miscellaneous.

No apparent damage.

SECRET

USS LST 220

TECHNICAL INSPECTION REPORT

SECTION III - ELECTRICAL

GENERAL SUMMARY OF ELECTRICAL DAMAGE

- I. Target Condition After Test.
 - (a) Drafts after test; list; general areas of flooding, sources.
 - 1. Drafts and list were the same as before test Baker.
 - 2. There was no flooding.
 - (b) Structural damage.

There was no structural damage in way of electrical equipment.

(c) Other damage.

No damage occurred to electrical equipment due to test B.

- II. Forces evident and Effects Noted.
 - (a) Heat.

There was no evidence of heat in way of electrical equipment.

(b) Fires and explosions.

There were no fires or explosions in way of electrical equipment.

(c) Shock.

There was no evidence of shock in way of electrical equipment.

SECRET

LST 220

(d) Pressure.

There was no evidence of pressure in way of electrical equipment.

(e) Effects peculiar to the Atom Bomb.

Evidence of radioactivity was the only effect noted which was peculiar to the Atom Bomb.

III. Effects of damage.

- (a) Effect on electrical machinery and ship control.

 No damage was apparent to electrical machinery or ship control.
 - (b) Effect on gunnery and fire control.No damage was apparent to gunnery and fire control.
- (c) Effect on watertight integrity and stability.

 No electrical damage affected watertight integrity or stability.
 - (d) Effect on personnel and habitability.

 No electrical damage affected personnel or habitability.
 - (e) Total effect on fighting efficiency.

No electrical damage affected the fighting efficiency of the vessel.

IV. General Summary of Observers Impressions and Conclusions.

No damage was evident on any electrical equipment on this vessel. It appears that present electrical equipment has sufficient shock

SECRET

LST 220

Page 22 of 31 Pages

resistance to withstand the effects of the B Bomb at the distance of this vessel from the center of the blast.

V. Recommendations.

None.

SECRET LST 220

Page 23 of 31 Pages

DETAILED DESCRIPTION OF ELECTRICAL DAMAGE

- A. General Description of Electrical Damage.
 - (a) Overall condition.

The overall condition of the electric plant is the same as before the test.

(b) Areas of major damage.

None.

- (c) Primary causes of damage in each area of major damage.

 None.
- (d) Effect of target test on overall operation of electric plant.
 - 1. Ship's service generator plant: No effect.
 - 2. Engine and boiler auxiliaries: No effect.
 - 3. Electric propulsion: Not applicable.
 - 4. Communications: No effect.
 - 5. Fire control circuits: No effect.
 - 6. Ventilation: No effect.
 - 7. Lighting: No effect.
- B. Electric Propulsion Rotating Equipment.

Not applicable.

C. Electric Propulsion Control Equipment.

Not applicable.

D. Ship's Service Generators.

No damage.



E. Emergency Generators.

Not applicable.

F. Switchboards, Distribution and Transfer Panels.

No damage.

G. Wiring, Wiring Equipment and Wireways.

. No damage.

H. Transformers.

Not applicable.

I. Submarine Propelling Batteries.

Not applicable.

J. Portable Batteries.

No damage.

K. Motors, Motor Generator Sets and Motor Controllers.

No damage.

L. Lighting Equipment.


No damage.

M. Searchlights.

No damage.

N. Degaussing Equipment.

No damage.



LST 220

O. Gyro Compass Equipment.

No damage.

P. Sound Powered Telephones.

No damage.

Q. Ship's Service Telephones.

Not applicable.

R. Announcing Systems.

No damage.

S. Telegraphs.

No damage.

T. Indicating Systems.

No damage.

U. I.C. and A.C.O. Switchboards.

Not applicable.

V. F.C. Switchboards.

Not applicable.



CONFIDENTIAL

LST 220

SECTION IV

PHOTOGRAPHS


TEST BAKER



USS LST 220

Page 27 of 31. Pages

CONFIDENTIAL



AB-CR-227-289-135. View from off port bow after Test B.




CONFIDENTIAL

Page 28 of 31 Pages

USS LST-220

9085



AB-CR-227-289-131. View from off starboard quarter after Test B.



CONFIDENTIAL

Page 29 of 31 Pages

USS LST-220

APPENDIX

COMMANDING OFFICERS REPORT

TEST BAKER



USS LST 220

Page 30 of 31 Pages

CONFIDENTIAL



COMMANDING OFFICERS REPORT

REPORT # 5

SECTION I

I have to report that upon reboarding LST 220 on 13 August 1946, no evidence of damage resulting from Test B was found.

All rigging, paint work, machinery, and hull structures were intact. No circuits were energized and no machinery was run, but visual inspection of all showed them to be in good condition.

STERET

USS LST 220

Page 31 of 31 Pages

UNCLASSIFIED



Defense Special Weapons Agency 6801 Telegraph Road Alexandria, Virginia 22310-3398

TRC

18 April 1997

MEMORANDUM FOR DEFENSE TECHNICAL INFORMATION CENTER ATTENTION: OMI/Mr. William Bush (Security)

SUBJECT: Declassification of Reports

The Defense Special Weapons Agency has declassified the following reports:

/ ✓AD-366588 ⁴	XRD-203-Section 12✓
AD-366589 -	XRD-200-Section 9
AD-366590 ∟	XRD-204-Section 13
AD-366591 ►	XRD-183
✓ ✓ AD-366586 ﴿	XRD-201-Section 10
V AD-367487. K	XRD-131-Volume 2-
√AD-367516 屮	XRD- ₹ 143 ✓
VAD-367493 K	XRD-142 ►
AD-801410L	XRD-138✓
AD-376831L 🗸	XRD-83►
AD-366759	XRD-80
√ ∠ AD-376830L ↓	XRD-79 ✔
✓AD-376828L 싹	XRD-76/
✓VAD-367464.X	XRD-106 ✓
AD-801404L	XRD-105-Volume 1
/ AD-367459 X	XRD-100/

Subject: Declassification of Reports

√✓ AD-367517 **¾** XRD-141 ✓ AD-366762 XRD-84 AD-366760 XRD-81 AD-366761 XRD-82 AD-367501 🗸 XRD-158-Volume 1 AD-367507L 🗸 XRD-152-Volume 4 ✓ AD-367495 🖟 XRD-184 ► ✓AD-367485 ₩ XRD-129℃ /AD-367484 H XRD-128 ✓ **✓**AD-367483 **✗** XRD-127℃ **√**AD-367482**火** XRD-126► AD-367488 XRD-132 AD-367480 XRD-124~ AD-801409L√ XRD-135 ► ✓AD-367490**火** XRD-136 ► ✓ AD-367492 🐧 XRD-137► AD-801411L V XRD-139 ₩ ✓AD-367518 **X** XRD-140 ✓ AD-367515 **√** XRD-144 AD-367514 ¥ XRD-145

✓AD-367468 🔏

AD-367513**√**

✓AD-367497**X**

XRD-110-Volume 2 ✓

XRD-146

XRD-162'

TRC

Subject: Declassification of Reports

AD-801406L Y XRD-114:

In addition, all of the cited reports are now approved for public release; distribution statement "A" now applies.

ARDITH JARRETT
Chief, Technical Resource Center